

TEST REPORT

 Report No.:
 HC10113/2024

 Page:
 1
 of
 12

 Date:
 March 12, 2024

7STARLAKE CO., LTD. 2F., NO.190, SEC. 2, ZHONGXING RD., XINDIAN DIST., NEW TAIPEI CITY, TAIWAN

The following merchandise was submitted and identified by the vendor as:

Product Description:	SYSTEM
Style / Item No.:	AV800/AVR800-X1A / SR2021031901006
Quantity:	Total 1 piece
Testing Period:	Jan. 23, 2024 to Feb. 29, 2024
Note:	(Client's declaration) AV800 for global Market/ AVR800-X1A for Israel Market

We have tested the submitted sample(s) as requested and the following results were obtained: Test Required: (According to client's test specification, please see following sheets in detail.)

- 1. Non-operating Altitude Test--I
- 2. Non-operating Altitude Test--II
- 3. Operating Altitude Test
- 4. Blowing Dust Test

Test Results: – PLEASE SEE ATTACHED SHEETS –

Signed for and on behalf of SGS TAIWAN Ltd.

Alex Chen Asst. Supervisor

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com.tw/Terms-and-Conditions</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/en/terms-and-conditions</u> and, for electronic format issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest externt / No 21. Write the company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest externt / No 21. Write the company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest externt / No 21. Write the under the limitation forme to the law.

> <mark>SGS Taiwan Ltd.</mark> 台灣檢驗科技股份有限公司_

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.sgs.com.tw



Report No.:	HC10113/2024		24
Page:	2	of	12

Reliability Laboratory

1. Non-operating Altitude Test--I:

Test Equipment:

Name	Brand	Model	Serial No.
Altitude chamber	GIANT FORCE	GTP-1260-50-CP-AR	MAF1206-008
			-

Lab Environmental Conditions:

Ambient temperature:	<u>(25 ± 3) °C</u>
Ambient humidity:	(55 ± 20) % RH

Test Location:

No.33, Wu Chyuan Road, New Taipei Industrial Park, WuKu District, New Taipei City, Taiwan.

Test Method/ Specification:

Test Method: MIL-STD-810G: 2008, Method 500.5 Procedure I and client's request.

Test Procedure:

Step	Temperature (°C)	Altitude (ft)	Time (minutes)
1	25	0	_
2	25	0	30
3	$25 \rightarrow 71$	$0 \to 15,000$	46
4	71	15,000	60
5	$71 \rightarrow -33$	15,000	104
6	-33	15,000	60
7	$-33 \rightarrow 25$	$15,000 \rightarrow 0$	58
8	25	0	10
Fest cy	cle: Total 1 cycle		

- Sample condition: Non-Operating
- Examine the appearance of the specimen(s) by visual check and perform functional check after this test.
- Functional check: Connect the specimen(s) with rated power and examine whether the booting function of specimen could be work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,可時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com.tw/Terms-and-Conditions</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/ent/erms-and-Conditions</u> and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.sgs.com.tw



TEST REPORT

Report No.:	HC10113/2024		24
Page:	3	of	12

Specimen:

AV800/AVR800-X1A / SR2021031901006

Style / Item No. : Quantity :

Total 1 piece

Test Result:

Check Item Style / Item No.	Appearance Check (visual check)	Functional Check
AV800/AVR800-X1A / SR2021031901006	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC10113/2024		24
Page:	4	of	12

2. Non-operating Altitude Test--II:

Test Equipment:

Name	Brand	Model	Serial No.
Altitude chamber	GIANT FORCE	GTP-1260-50-CP-AR	MAF1206-008
			7

Lab Environmental Conditions:

Ambient temperature:	<u>(25 ± 3) °C</u>
Ambient humidity:	<u>(55 ± 20) % RH</u>

Test Location:

No.33, Wu Chyuan Road, New Taipei Industrial Park, WuKu District, New Taipei City, Taiwan.

Test Method/ Specification:

Test Method: MIL-STD-810G: 2008, Method 500.5 Procedure I and client's request.

Test Procedure:

Step	Temperature (°C)	Altitude (m)	Time (minutes)
1	25	0	_
2	25	0	30
3	$25 \rightarrow 71$	$0 \rightarrow 2,500$	46
4	71	2,500	60
5	$71 \rightarrow -20$	2,500	91
6	-20	2,500	60
7	$-20 \rightarrow 25$	$2,500 \rightarrow 0$	45
8	25	0	10
Test cy	cle: Total 1 cycle		

- Sample condition: Non-Operating
- Examine the appearance of the specimen(s) by visual check and perform functional check after this test.
- Functional check: Connect the specimen(s) with rated power and examine whether the booting function of specimen could be work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,可時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/en/terms-and-conditions/terms-end-conditions/terms-end-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.sgs.com.tw



TEST REPORT

Report No.:	HC	10113/20	24
Page:	5	of	12

Specimen:

AV800/AVR800-X1A / SR2021031901006

Quantity :

Style/ Item No. :

Total 1 piece

Test Result:

Check Item	Appearance Check (visual check)	Functional Check
Style / Item No. AV800/AVR800-X1A / SR2021031901006	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC1	0113/20	24
Page:	6	of	12

3. Operating Altitude Test:

Test Equipment:

Name	Brand	Model	Serial No.
Altitude chamber	GIANT FORCE	GTP-1260-50-CP-AR	MAF1206-008

Lab Environmental Conditions:

Ambient temperature:	<u>(25 ± 3) °C</u>
Ambient humidity:	<u>(55 ± 20) % RH</u>

Test Location:

No.33, Wu Chyuan Road, New Taipei Industrial Park, WuKu District, New Taipei City, Taiwan.

Test Method/ Specification:

Test Method: MIL-STD-810G: 2008, Method 500.5 Procedure II and client's request.

Test Procedure:

Step	Temperature (°C)	Altitude (m)	Time (minutes)
1	25	0	_
2	25	0	30
3	$25 \rightarrow 55$	$0 \rightarrow 2,500$	30
4	55	2,500	60
5	$55 \rightarrow -20$	2,500	75
6	-20	2,500	60
7	$-20 \rightarrow 25$	$2,500 \rightarrow 0$	45
8	25	0	10
Test cy	cle: Total 1 cycle		

- Sample condition: Operating
- Examine the appearance of the specimen(s) by visual check and perform functional check after this test.
- Functional check: Connect the specimen(s) with rated power and examine whether the booting function of specimen could be work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com.tw/Terms-and-Conditions</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/ent/erms-and-Conditions</u> and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.sgs.com.tw



TEST REPORT

Report No.:	HC	10113/20	24
Page:	7	of	12

Specimen:

Style / Item No. : Quantity :

AV800/AVR800-X1A / SR2021031901006 Total 1 piece

Test Result:

Check Item Style / Item No.	Appearance Check (visual check)	Functional Check
AV800/AVR800-X1A/ SR2021031901006	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC1	0113/20	24
Page:	8	of	12

4. Blowing Dust Test:

Test 1	Equi	pment:

Name	Brand	Model	Serial No.
Chamber	ACS	SD 8000 MIL	TT02038
Anemometer	INNPITRON	RG4000WS	FS22082507
Concentration meter	SICK	DHT-T00	16488579
DC Power Source	NF	KP3000GS	9174266

Lab Environmental Conditions:

Ambient temperature:	(25 ± 3) °C
Ambient humidity:	<u>(55 ± 20) % RH</u>

Test Method/ Specification:

Test method:	MIL-STD-810G: 2008, Method 510.5, Procedure I and client's request
Sample condition:	<u>1. Operating at (25 ± 2) °C</u>
	2. Operating at (55 ± 2) °C
Test temperature:	<u>1. (25 ± 2) °C</u>
	<u>2. (55 ± 2) °C</u>
Dust concentration:	$(10.6 \pm 7) \text{ g/m}^3$
Air flow velocity:	8.9 m/s (1750 ft/ min) which is approximately 20 mph.
Test duration:	<u>12 hours [6 hours for (25 ± 2) °C and 6 hours for (55 ± 2) °C</u>

- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Connect the specimen(s) with rated power and examine whether the booting function of specimen could be work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sgs.com/ent/erms-and-Conditions</u> of telectronic Documents at <u>www.sgs.com/ent/erms-and-Conditions</u> of telectronic becaments at <u>www.sgs.com/ent/erms-and-Conditions</u> of telectronic documents, and urisdiction sitems and conditions to the company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullex.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.sgs.com.tw



TEST REPORT

Report No.:	HC10113/2024		
Page:	9	of	12

Specimen:

Style / Item No. : Quantity :

AV800/AVR800-X1A / SR2021031901006 Total 1 piece

Test Result:

Check Item Style / Item No.	Appearance Check (visual check)	Functional Check
AV800/AVR800-X1A/ SR2021031901006	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.




Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC10113/2024		
Page:	10	of	12

Test Photos:




Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC10113/2024		
Page:	11	of	12

Test Photos--Continued:




Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC10113/2024		
Page:	12	of	12

Test Photos--Continued:



The End of Test Report

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558